


Isabella County Time of Transfer Environmental Health Impact 2022 Report

450

Onsite sewage treatment systems and drinking water wells evaluated.



73%

Of onsite sewage treatment systems functioning properly.

78%

Of drinking water wells that were designed, maintained, and providing safe water in adequate quantity.



3

Homes identified as discharging untreated wastewater to stream, ditch, or field tile representing approximately 328,500 to 492,750 gallons of wastewater a year no longer being discharged into our waterways.

57

Homes with sewage surfacing, backing up, damaged septic tank, laundry or kitchen waste discharging on the ground surface.



Sewage surfacing at end of drainfield

6

Sewage disposal systems located less than 50 feet to a drinking water well or surface water. A minimum of 50 feet is the established standard to ensure bacteria and viruses are killed before they can contaminate our water.



Cracked septic tank

